

# Change Notice

# P Series

## Changes to Location & Production for P Toggles & Rockers

Type of Change:

- Engineering     Part Number  
 Product         Appearance

There will be revisions to the production and manufacture location for P Toggles and Rockers to include standard, UL approved, and custom part numbers. "Japan" will not be on the side of the switches, and the older logo will be updated. The lot code with no dot mark will be replaced with a dot mark above the first digit. The shipping box for P Toggles and Rockers has "JAPAN FACTORY" on the side, but will be replaced with "CHINA FACTORY." The switches with the UL approval symbol with factory code "11" will have the code revised to "078."



Changes for P Series Toggles & Rockers

Example: P2011	Identification on Switch	Lot Number	Shipping Box	UL Symbol
<b>Before Changes</b>	Place of Manufacture & Logo "Japan" Older NKK Logo	Lot Number without Dot Mark  65	"JAPAN FACTORY" printed on side of box	UL Approval with Factory Code "011"  
<b>After Changes</b>	Place of Manufacture Removed, Logo Updated "Japan" Removed NKK Logo Updated	Lot Number with Dot Mark Above First Digit  65	"CHINA FACTORY" printed on side of box	UL Approval with Factory Code "078"  

**Notes**

See page 2 for P Series effected part numbers.  
 There are no changes to the switches' dimensions or specifications.  
 The location of the Lot Number on switch case may vary depending on the part number.  
 Contact the factory if more details are needed.

**Effective Dates**

Changes to P Series Toggles and Rockers will be effective December 2016.

**NKK SWITCHES CO., LTD.** <http://www.nkk.com> E-mail: [nkkswitches@nkkswitches.co.jp](mailto:nkkswitches@nkkswitches.co.jp)

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

# Change Notice

# P Series

## Changes to Location & Production for P Toggles & Rockers

### Standard P Series Toggles

P2011	P2012	P2013	P2021	P2022	P2023
P2011B	P2012B	P2013B	P2021B	P2022B	P2023B
P2011BP	P2012BP	P2013BP	P2021BP	P2022BP	P2023BP
P2011BZ	P2012BZ	P2013BZ	P2021BZ	P2022BZ	P2023BZ
P2011D	P2012D	P2013D	P2021D	P2022D	P2023D
P2011DP	P2012DP	P2013DP	P2021DP	P2022DP	P2023DP
P2011DZ	P2012DZ	P2013DZ	P2021DZ	P2022DZ	P2023DZ
P2011E	P2012E	P2013E	P2021E	P2022E	P2023E
P2011EP	P2012EP	P2013EP	P2021EP	P2022EP	P2023EP
P2011EZ	P2012EZ	P2013EZ	P2021EZ	P2022EZ	P2023EZ
P2011P	P2012P	P2013P	P2021P	P2022P	P2023P
P2011Z	P2012Z	P2013Z	P2021Z	P2022Z	P2023Z

### Standard P Series Rockers

P2011N	P2012N	P2013N	P2021N	P2022N	P2023N
P2011NP	P2012NP	P2013NP	P2021NP	P2022NP	P2023NP
P2011NZ	P2012NZ	P2013NZ	P2021NZ	P2022NZ	P2023NZ
P2011Y	P2012Y	P2013Y	P2021Y	P2022Y	P2023Y
P2011YP	P2012YP	P2013YP	P2021YP	P2022YP	P2023YP
P2011YZ	P2012YZ	P2013YZ	P2021YZ	P2022YZ	P2023YZ

### Standard P Series Toggles with UL Approval

P2011/U	P2012/U	P2013/U	P2021/U	P2022/U	P2023/U
P2011B/U	P2012B/U	P2013B/U	P2021B/U	P2022B/U	P2023B/U
P2011BP/U	P2012BP/U	P2013BP/U	P2021BP/U	P2022BP/U	P2023BP/U
P2011BZ/U	P2012BZ/U	P2013BZ/U	P2021BZ/U	P2022BZ/U	P2023BZ/U
P2011D/U	P2012D/U	P2013D/U	P2021D/U	P2022D/U	P2023D/U
P2011DP/U	P2012DP/U	P2013DP/U	P2021DP/U	P2022DP/U	P2023DP/U
P2011DZ/U	P2012DZ/U	P2013DZ/U	P2021DZ/U	P2022DZ/U	P2023DZ/U
P2011E/U	P2012E/U	P2013E/U	P2021E/U	P2022E/U	P2023E/U
P2011EP/U	P2012EP/U	P2013EP/U	P2021EP/U	P2022EP/U	P2023EP/U
P2011EZ/U	P2012EZ/U	P2013EZ/U	P2021EZ/U	P2022EZ/U	P2023EZ/U
P2011P/U	P2012P/U	P2013P/U	P2021P/U	P2022P/U	P2023P/U
P2011Z/U	P2012Z/U	P2013Z/U	P2021Z/U	P2022Z/U	P2023Z/U

### Standard P Series Rockers with UL Approval

P2011N/U	P2012N/U	P2013N/U	P2021N/U	P2022N/U	P2023N/U
P2011NP/U	P2012NP/U	P2013NP/U	P2021NP/U	P2022NP/U	P2023NP/U
P2011NZ/U	P2012NZ/U	P2013NZ/U	P2021NZ/U	P2022NZ/U	P2023NZ/U
P2011Y/U	P2012Y/U	P2013Y/U	P2021Y/U	P2022Y/U	P2023Y/U
P2011YP/U	P2012YP/U	P2013YP/U	P2021YP/U	P2022YP/U	P2023YP/U
P2011YZ/U	P2012YZ/U	P2013YZ/U	P2021YZ/U	P2022YZ/U	P2023YZ/U

**NKK SWITCHES CO., LTD.** <http://www.nkk.com> E-mail: [nkkswitches@nkkswitches.co.jp](mailto:nkkswitches@nkkswitches.co.jp)

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031